



5th July 2010

To whom it may concern,

International Paint Intersleek® Underwater Cleaning Equipment Evaluation

Charles Cleghorn Limited has successfully completed International Paint's Intersleek® underwater cleaning panel tests using the following equipment and set-up parameters.

Company	Contact Details	Equipment Tested
Charles Cleghorn Limited	Charles Cleghorn Limited Church Farmhouse High Street Croydon Royston SG8 0DN Tel +44 (0)1223 208384 E-mail ccleghornltd@yahoo.co.uk	Cavitation System: HG1222, Using petrol engine (Honda GX670 v twin 4-stroke 18kw). Working pressure 2,200psi (152 bar). Flow rate 45 l/min (12US gallons / min)

International Paint recommends that the vessel operator using this cleaning company checks that the correct equipment and suitably trained personnel are provided.

Yours faithfully
For and on behalf of International Paint Ltd.

Colin Watson
Worldwide Marine Technical Operations Manager

It is advised that only the specific equipment under the same operating conditions that were evaluated in the testing process and operated by trained experienced personnel should be used when cleaning Intersleek® vessels.

Whilst every effort has been made to ensure that any of our recommended Underwater Cleaning Contractors ("UWCC") comply with all relevant protocols of International Paint Limited ("International") to the extent permitted by law, International accepts no responsibility whatsoever for any loss, damage or other liability arising from the UWCC's actions.